else visiting the church.

## **Akeman Street Baptist Church**

# **RISK ASSESSMENT – External**

**Date:** 03/01/2023

Assessed By: David Crane		Signature:	Torceano		Review Date:	Annuall	Annually	
Review By:	John	Heasman	Signature:	John Heasman	Position:	Church Officer	Date:	03/01/2023
Description of assessment								
Location Details  Outside areas of the church (for example, garden, graveyard, car park, entrance etc).								
Who might be harmed  Members of the congregation, employees (including pre-school staff), Pre School Children/Parents, volunteers, contractors, visitors, and anyon								

Potential Hazard	Severity*	Probability*	Risk**	Actions to minimise risk	After minimising risk	
					Probability*	Risk**
Trips:  Uneven footpaths  Damaged paving stones and slabs  Worn, damaged or uneven steps  Gravestones, kerbs causing obstruction  Protruding tree roots and undergrowth  Poor lighting  Missing or defective handrails  Other	3	3	9	<ul> <li>Regular inspection of outside area.</li> <li>Ensure lights are on during necessary hours</li> <li>Tape on steps to improve visibility</li> <li>Inspection of handrails</li> </ul>	2	6

<sup>\* 1 =</sup> slight, 5 = high

<sup>\*\*</sup> Severity x Probability = Risk

Slips:						
<ul> <li>Poor drainage of footpaths</li> <li>Growth of algae or moss</li> <li>Accumulations of wet leaves or loose materials</li> <li>Inadequate precautions for adverse weather (for example snow, ice, etc.)</li> <li>Walk-in contaminant from adverse weather (for example mud, rainwater, etc.)</li> <li>Other</li> </ul>	2	3	6	<ul> <li>Regular inspection of outside areas and sweeping and removal of leaves (Duty member role)</li> <li>Salt spreading during snow/ice</li> </ul>	2	4
Headstones, Tombs and Monuments:  Damaged monuments Displaced headstones Other	3	3	9	<ul> <li>Professional inspection of graveyard, gravestones and monuments.</li> <li>Signage into graveyard (uneven ground)</li> </ul>	2	6
<ul> <li>Trees:</li> <li>Damaged or displaced trees</li> <li>Protruding tree roots</li> <li>Diseased/poisonous trees/plants</li> <li>Other</li> </ul>	2	2	4	<ul> <li>Regular inspection of trees and tree maintained undertaken bi- annually.</li> </ul>	2	4
Car Park:	2	4	8	Ensure light in carpark is on when necessary	2	4
<ul> <li>Work Equipment:         <ul> <li>Defective or poorly maintained power tools (for example, lawnmowers, strimmers, etc.)</li> <li>Defective or poorly maintained hand tools (for example, garden shears, hammers, saws etc.)</li> <li>Inexperienced operator</li> <li>Other</li> </ul> </li> </ul>	2	3	6	<ul> <li>Damaged tools reported</li> <li>Regular inspection of tools</li> <li>Tools stored in locked shed</li> <li>Use of professional contractors where skill required is outside of competence of church resource or statutory requirement (e.g. registered electrician)</li> </ul>	2	4

<sup>1 =</sup> slight, 5 = highSeverity x Probability = Risk

NOTE: Before reading this risk assessment please see guidance notes towards the end of the document.

<ul> <li>Hazard Substances:</li> <li>Maintenance products (for example, petrol, liquefied petroleum gas, etc.)</li> <li>Horticultural products (for example, pesticides, weedkillers, fertilisers, etc.)</li> <li>Other</li> </ul>	3	3	9	<ul> <li>Substances stored in locked shed with restricted access</li> <li>Insurer notified of hazardous substances</li> </ul>	2	6
Rodents	1	5	5	<ul> <li>Appoint contactor to expect premises and set and monitor traps.</li> <li>Ensure all sittings of rodents and droppings are reported immediately.</li> </ul>	2	2

### **Guidance Notes**

	5	5	10	15	20	25			
	4	4	8	12	16	20			
SE\	3	თ	6	9	12	15			
SEVERITY	2	2	4	6	8	10			
7	1	1	2	თ	4	5			
		1	2	3	4	5			
	PROBABILITY								

	PROBABILITY						
5	Almost Certain – Very High Risk						
4	Probable – High Risk						
3	50/50 – Medium Risk						
2	Improbable – Low Risk						
1	Almost impossible – Low Risk						

	SEVERITY					
5	Fatality – Very High Risk					
4	High Risk					
3	Medium Risk					
2	Low Risk					
1	Insignificant – Low Risk					

Risk Rating	1–4 LOW	5–9 MEDIUM	10-15 HIGH	16-25 VERY HIGH

#### Additional comments:

- 1. This risk assessment needs to be shared with all group leaders before they run a group to ensure compliance with all actions to minimise risk.
- 2. Groups leaders are to sign an acknowledgement sheet to show their understanding and compliance of this risk assessment.
- 3. The risk assessment is to be reviewed on an annual basis, or sooner if changes are made to church building, external areas, working practices or after an accident/near miss.
- 4. This risk assessment must be approved by the nominated Elder or Deacon for health and safety before being issued as a live document.
- \* 1 = slight, 5 = high

#### **Risk Assessment Acknowledgement sheet**

Name	Group(s)	Date	Signature

<sup>\* 1 =</sup> slight, 5 = high

<sup>\*\*</sup> Severity x Probability = Risk